



Tursdale Technical Services Ltd  
Unit N12B  
Tursdale Business Park  
Co. Durham  
DH6 5PG  
United Kingdom  
Phone: +44 ( 0 ) 191 377 3398  
Fax: +44 ( 0 ) 191 377 3357  
[info@tursdaletechnicalservices.co.uk](mailto:info@tursdaletechnicalservices.co.uk)  
<http://www.industrial-needs.com/>

## Manual PCE-SH500



PCE Group Iberica.S.L

SH Series Digital Push Pull Force Gauge


**(SH Series Technical Specifications)**

Model	SH-2	SH-5	SH-10	SH-20	SH-50	SH-100	SH-200	SH-500
Capacity	2N	5N	10N	20N	50N	100N	200N	500N
Resolution	0.001N	0.001N	0.005N	0.01N	0.01N	0.05N	0.1N	0.1N
Accuracy	$\pm 0.5\%$							
Unit	N,kgf,lbf							
Power	Ni-Hi 8.4V 1200mAh							
Sensor conformation	Sensor inside							
Work temperature	$20 \pm 10^{\circ}\text{C}$							
Carry temperature <sub>e</sub>	$-27^{\circ}\text{C} \sim +70^{\circ}\text{C}$							
Relative humidity	15% ~ 80% RH							
Work entirionment	No vibrancy and no cautory							

**SH Series Digital Push Pull Force Gauge**

**PCE Group Iberica.S.L**


**(SH Series Parts Apellation)**



**PCE Group Iberica.S.L**

**SH Series Digital Push Pull Force Gauge**

**( SH Series Dimension Unit/mm )**



SH Series Digital Push Pull Force Gauge

PCE Group Iberica.S.L


**Test Stands, No Included, Picture Only For Reference.**




SLJ




SPJ



SPH



SJH-500



SJV-5K




**Safety Precaution**

**CAUTION**

Wrong operation may damage the device or leads to serious result. There are important precautions and operation methods listed in our manual, so please read it before using the instrument. If shock load is tested, please choose the test stand with double load.

**WARNING**

1. In break down or shear test, wear protective mask to protect you from scattering pieces.
2. Do not use the damaged or warped clamps. Or this kind of clamps may be off or broken, leading the tested object fall on your foot.
3. When Error appears on the screen, the load has exceeded 110% of the capacity.
4. Do not use damaged or warped tools to press the button .



5. Do not load bending or twisting force on sensor.
6. Do not apply excessive load.Or the device will be damaged.

7. Do not use damaged or warped tips or hooks .
8. Do not use this gauge near water, oil or other liquids. Please store it in a dry and clean place.
9. Use adapted charger, or the electric break-down may happen even fire .
10. Use after inserting the AC charger into the socket .Any loose fitting may cause electric shock or fire.
11. Do not use the voltage exceeding the capacity , otherwise the electric shock or fire may happen.
12. Do not plug the adaptor with wet hand.

## **Functions**

SH series digital push pull force gauge ,with compact size and high accuracy, is easy to operate and handy to carry. It can be used not only for measuring tension/compression force but also for various testing purposes such as switch test , insertion/withdrawing test and fracture test. Furthermore, it can also be matched with test stands and clamps for multipurpose measurement.

## **characteristic**

- ※High accuracy and high resolution;
- ※Peak holding and auto-releasing;
- ※Upper and lower limit setting;
- ※Force direction indication;
- ※Blue background light;
- ※ Memorizing and calculating the average;
- ※ LCD screen direction turning;
- ※ Automatic power off
- ※ Units conversion

※ RS-232C output port


### Specification

Please refer to P1.

### Description of parts and function

Please refer to P2 for parts' description.

#### 1. The LCD display window



The meaning of symbols:

- ① Displaying the measured value; in setting mode, it is the set value.
- ② Units of push pull force gauge. Three units " N " " lbf " " kgf " are optional.
- ③ Printing all the reserved data.
- ④ Indication of power content.



- ⑤ "PEAK" means it is in the state of peak holding;  
"AUTO PEAK", means it is in the state of auto-releasing.
- ⑥ Auto calculating the average and the indication symbol in setting mode.
- ⑦ Symbol of force direction  
"↑" means tensile test and "↓" means compressive test.
- ⑧ Memorizing the test value.  
The force gauge can memorize 10 tested value . There are 10 grids on the LCD and each of them memorizes one tested value ."▶" Means the showing value and "✓" means the tested value has been saved .
- ⑨ Symbol of average

## 2. The function of buttons



Picture A





Picture B Testing Reading Can Turn display






On/off button

**SH Series Digital Push Pull Force Gauge****PCE Group Iberica.S.L**

- ZERO** Zero button  
Press unit key for 3 seconds the LCD screen will change its direction.
- UNIT** Unit  
Three units are optional and convert automatically
- PEAK** Peak  
Switch of peak mode, peak holding, semi-peak holding and track.  
Track mode is default when the gauge is on.
- PRINT** Print  
A. When RS-232C is set at "print" , pressing this button prints the  
test data and analysis report.  
B. When RS-232C is set at "PC" , pressing this button and the " print"  
will will transmits the test data to computer.
- MEMORY** Memory  
Memorize the tested value and calculate the average of memorized data.
- SET** Setting  
A. Pressing " set" button the first time, "HIDT" will appear on  
the LCD and the upper limit is set. Pressing "□□" changes the  
value. Pressing "set" button the second time, "LODT" shows on  
the LCD and the lower limit is set.  
B. Pressing " SET" button the third time, "LE.SET" shows on the  
LCD and the data showed is the min memorized value. Pressing  
"□□" changes the (In the test, the data which is less than the min  
memorized value will not be memorized.)  
C. Pressing "set" the fourth time, the "P.OFF" will show on the  
LCD and the time of auto clean peak appear on the value display.  
D. Pressing " set" the fifth time, the "A.PE" will display on the  
LCD and the time of auto clean peak appear Pressing " set" the  
fifth, on the value display.  
E. Pressing " set" the sixth time, the screen will show "rs232" and  
data frame will show "pc" or "print" . Pressing "□□" changes the  
mode, "PC" means outputting the data to computer with RS-232C  
output; "Print" means transferring the data to printer. Pressing  
" set" button the seventh time saves the setting.

-  Add 1 (the display direction changed is reduce 1)/background light switch
  - A. In memory mode, press it one time, symbol will forward one case.
  - B. In setting mode, press it one time, the value will increase one.
  - C. In the average mode, It is the switch of the background illumination.
-  Reduce 1 (the display direction changed is add 1)/delete
  - A. In memory mode, press it one time, symbol will backward one case.
  - B. In setting mode, press it one time, the value will decrease one.
  - C. In the average mode, press it one time, all of memory data will be deleted

### 3. The Pilot lamp of upper and lower limit.

-  Pilot lamp of upper limited alarm
-  Pilot lamp of normal
-  Pilot lamp of lower limited alarm

### 4. Communicating port

RS-232C series port output the value data to PC or printer.

### 5. Power connecter



Suitable power adaptor with 12v DC ,300MA .


### 6.Reset hole

It is to restart the gange, when the gauge is strongly disturbed.

## Preparation before operation

### 1. Check the power supply

When the power is on, check the battery. If the Ni-Hi batteries power is low,  appears on the screen. Please charge battery by connecting AC adapter. Charge the battery as follows: Connect the AC adapter with the gauge first and then connect the adapter to 220V/50HZ power supply. Right after the charging started,  is displayed. Charging time: 4 hours. Measurement during charging is possible and the battery can be charged when the power is on or off.



## 2. Installing measuring tips

Please choose the best tip and fix it on the measuring shaft. Do not screw the measuring tip too forcibly, or the sensor would be damaged.

## Testing

### 1. Turning on the power

When the power is off, connect the power and press "oFF/ON" button to make the power on. Then the screen will show "SUNDOO" and the model of this gauge, and that means the gauge is in normal condition. When the measuring tip loads the object with not over 5% of the load capacity, the gauge has the automatic cleaning zero function; on the contrary, when the object is over 5% of the load capacity, error may happen so please use light tips. When the power is on, pressing button makes the power off. The gauge will turn off "oFF/ON" itself after the set time when it is not in operation.

### 2. Zero cleaning

After the gauge is turned on, pressing "ZERO" cleans the zero after the reading the stable. The range of zero cleaning is  $\pm 5\%$  of the capacity. Pressing cleans the peak while it "ZERO" is in peak-holding mode and saves the set value in setting mode.

### 3. Test mode choosing

The force gauge provides three kinds of test modes: track mode, peak holding mode and auto-releasing of peak. The track mode is default when the gauge is turned on and there is no "PEAK" on the screen. After pressing "PEAK", the screen will show "PEAK" and it is in peak-holding mode and the value showed on the gauge is the max value the shaft can bear. Pressing "AUTO PEAK" and the auto-releasing of peak will be delayed. The reasing is the max value the sensor can stand. The reading will be cleaned after 1-10 seconds. The three mode can exchange when the "PEAK" is pressed every time.

### 4. Selection of unit

Pressing "UNIT" converts the units: N, kgf and lbf.




5. Setting upper and lower limits, min captured peak value, auto power off time and RS-232C output connection.

- a. Pressing set button the first time makes the screen display "HIDT" and the upper limit is showed in the digital frame. Pressing "set" button the second time makes the screen display lodt and the lower limit is showed in the digital frame. Pressing "▲▼" changes the value.
- b. Pressing "set" the third time makes the screen show "LE.SET" and the min captured peak value is displayed in the digital frame. Pressing "▲▼" changes this value. Data which is less than this value will not be memorized.
- c. Pressing "set" the forth time makes the screen show "P.OFF" and the digital fram will show the time of auto power off. Pressing "▲▼" changes the value.
- d. Pressing "set" the fifth time makes the screen show "A.PE" and the digital frame will show the peak auto-releasing time. Pressing "▲▼" changes the value.
- e. Pressing "set" the sixth time ,makes the screen show "RS232" and "PC" or "Print" will be showed in the digital frame. Pressing "▲▼" changes the value. "PC" means outputing the data to computer with RS-232C output; "Print" means transferring the data to printer to printing the 10 memorized data.

### B. Testing

Please hold the gauge or fix it on a suitable test stand. Keep the gauge and the measured object in a line, otherwise the value will not be correct.



### C. After testing

After the test is finished, turn off the power and take off the measuring

tip, then clean and put all the parts and accessories of the gauge into the case.

### Test stands its appurtenance

This gauge can be fixed with various test stands for multi-purpose, testing insertion/withdrawing force, push pull force and fracture test.

### After Measure


Turn off the power source after your measurement. Then clean and put all the parts and accessories in the carrying case for next time to use.

### Test stand & Appurtenance


This gauge can be fixed with various test stand as multipurpose test stand for measurement of tension/compression force, insertion/withdraw test, and fracture test, etc. (View the page 4)

### About Memory & Peak Capture Line

If you need to use the memory function, Please set the Peak capture line "F". In the test, the gauge will remember the Peak value, which is above "F". The value is absolute value. When the force is over than  $F_0$ , the memory function start to memory the max value in the test; the force is less than again, one time of test is  $F_0$  completed. If the peak value is lower that "F" in one test, the peak value is not memorized.



When peak value is saved, the saved case will show " ✓ ", and the " ▶ " will be up to lower location. The gauge can memorize 10 values. If the value is more than 10 values, the new value cover original



Needle	Signal	Illustration
2	TxD	Output signal of scm
3	RxD	Incept signal of scm
5	GND	Earib
6	+2V	Over upper limit
7	+2V	Lower than lower limit
8	+2V	Ok is the eligible

1. When RS-232C output is set at "Print", the print will flicker when "Print" is pressed and ten groups of data and analysis report will be printed. Please refer to the picture on right.

Title	SH-500 TEST REPORT:-----
Data for memo	DATE:
No	NO:
Unit of value	UNIT: N
Upper limit	HIDT: 420.5
Lower limit	LODT: 222.1
Peak capture line	LE. SET: 10.0
The test value or data + is over upper limit, - is the lower than lower limit, Ok is the eligible	01 150.2 -
	02 198.3 -
	03 450.5 +
	04 85.5 -
	05 256.8 OK
	06 270.8 OK
	07 266.6 OK
	08 400.2 OK
	09 368.9 OK
	10 286.5 OK
Max value	MAX: 450.5
Min. Value	MIN: 85.5
Average value	AVERAGE: 273.4


2. When RS-232C output is set at PC, the Print will flicker and when "Print" is pressed, ten groups of data will be transmitted to computer. Specific method of connecting apparatus and computer is in the Following:

- A. Connect the push pull force gauge to PC with RS-232 cable;
- B. Turn on the gauge and make it on the working state, then set RS-232C to the state of output to PC. Please refer to the in P13.


## SH Series Digital Push Pull Force Gauge

PCE Group Iberica.S.L

- C. Insert the accessory CD into computer and open the following path:CD-ROM drive\Chinese\SH and ST port software\SundooPort\SundooPort.exe;This software need not be installed, and you only have to copy the SundooPort folder to computer hard disc and then double click it.
- D. Single click the tool on menu columnparameteroptional dialogue column, then set the parameter(picture 1). Choose the port: COM1 or COM2 which correspond to the port line.
- E. Data can be received by pressing " print " on the torque meter. Refer to picture2.
- F. Preserve the tesed data and the format is excel electronic form and TXT plaine text form.




(Picture 1)



(Picture 2)





Test No.	1	2	3	4	5	6	7	8	9	10
Value:	18.3	14.3	7.7	15.3	19.5	12.7	22.2	22	19.9	21
Max:	22.2									
Min:	7.7									
Average:	16.3									

(Picture 3)

### Appearance & Install Size

View the page 3.

### Charging battery

This gauge is used Ni-Hi batteries with 8.4V/1200mA as power. The fully charged battery can work in 12 hours continuously . If Ni-Hi batteries power are low, [LO BAT] appears on the display.

Please charge battery by adapter, the adapter is 12V.DC/300mA.which is provided with the force gauge in 4 hours.

### Cautious

1. The frequent and long time charging battery will shorten life of battery.
2. Please charge the battery after exhaust the power, that will cancel remember effect .
3. You can use the gauge in charge battery.
4. The life of battery: charge/discharge over 500 times, with normally operation.

### Charging Batteries

**Packing list**

Item	Parts name	Quantity
1	Main body	1
2	AC adapter	1
3	M3X8 Screws	4+1
4	Extensive Shaft	1
5	CD-ROW	1
6	Users manual	1
7	Qualification certificate	1
8	Accessories	5

**Maintains**

1. Clean dirt and dust from gauge with soft cloth. After dipping cloth in the Neutral detergent water and squeeze out water, and clean dirt with the Cloth.  
Do not use volatile chemical liquid to clean the gauge, such as benzene, thinner, alcohol, etc.
2. Handle carefully during use and carry.
3. Never disassemble, repair, and remodel the gauge yourself.  
Should you perform any if do as these, that may cause malfunction of the gauge.
4. If malfunction, please contact original sale department or out company.

In this direction will find a vision of the measurement technique:  
<http://www.industrial-needs.com/measuring-instruments.htm>

**NOTE:** "This instrument doesn't have ATEX protection, so it should not be used in potentially explosive atmospheres (powder, flammable gases)."